

- WINDOW REQUIRING REMOVAL
- WINDOW APPROVED, NO REMOVAL REQUIRED



3

EAST INTERIOR ELEVATION

$\frac{1}{32}'' = 1'-0''$



4

WEST INTERIOR ELEVATION

$\frac{1}{32}'' = 1'-0''$



1

WEST ELEVATION

$\frac{1}{32}'' = 1'-0''$



2

EAST ELEVATION

$\frac{1}{32}'' = 1'-0''$

Consultant



Texas Capitol

Exterior Preservation Project

1100 N Congress Avenue Austin TX 78701

Architect: State Preservation Board

Sheet Number

Mark	Date	Description
	1/13/16	Added callouts for unsurveyed windows. Various corrections to match correctly to survey.
	5/16/16	Various corrections to match updated surveys, pulls, and window inspection approvals.

Sheet Number
ELEVATIONS

Sheet Number

A302

Date: 5/16/16